

INTERMOUNTAIN POWER UNIT #2 TURBINE-GENERATOR VIBRATION ANALYSIS

<u>HP Rotor (T1 & T2)</u>	Static: 0.6 mils Couple: 3.7 mils	Correction: None. Rotor being replaced. Correction: None. Rotor being replaced.
<u>A Coupling</u>	Static: 2.6 mils	Correction: Wait for data with new HP rotor. The "A" Coupling vibration is being adversely influenced by the present HP rotor vibration.
<u>IP Rotor (T3 & T4)</u>	Static: 2.0 mils Couple: 1.7 mils	Correction: Mid-span: Add 2 standard factory weights centered @ 76°. (Approximately 12 oz total) The Low Speed Balance during the overhaul will take care of this. Correction: None, unless the Low Speed Balance during the overhaul indicates a correction is needed
<u>B Coupling</u>	Static: 0.3 mils	Correction: None.
<u>LPA Rotor (T5 & T6)</u>	Static: 0.5 mils Couple: 1.5 mils	Correction: None. Correction: #5 Bearing End: Add 6 oz @ 284°. #6 Bearing End: Add 6 oz @ 104°.
<u>C Coupling</u>	Static: 0.7 mils	Correction: None.
<u>LPB Rotor (T7 & T8)</u>	Static: 0.3 mils Couple: 1.2 mils	Correction: None. Correction: #7 Bearing End: Add 6 oz @ 239°.
#8 Bearing End: Add 6 oz @ 59°.		
<u>D Coupling</u>	Static: 0.5 mils	Correction: None.
<u>LPC Rotor (T9 & T10)</u>	Static: 1.4 mils	Correction: None. 1 st critical vibration is low.